


工事名 古河アパート1号棟他長寿命化工事

	【外壁改修】 外壁の塗替え → 耐久性の向上	【外壁改修】 外壁の塗替え → 耐久性の向上	【防水改修】 屋上防水の改修 → 耐久性の向上
工事実施前			
工事実施後			

工事名 古河アパート1号棟他長寿命化工事

	【外壁改修】 外壁の塗替え → 耐久性の向上	【外壁改修】 外壁の塗替え → 耐久性の向上	【防水改修】 屋上防水の改修 → 耐久性の向上
工 事 実 施 前	 A wide-angle photograph of a four-story apartment building with a white facade and balconies. A white van is parked in the foreground parking lot.	 A close-up view of the side of the apartment building, showing the white exterior wall and a balcony. The number '2' is visible on the upper part of the wall.	 A view of the flat roof of the apartment building, showing a dark, weathered surface with a central antenna tower and various pipes.
工 事 実 施 後	 A wide-angle photograph of the same apartment building after renovation, showing a fresh white facade and balconies. A silver car and a white van are parked in the foreground.	 A close-up view of the side of the apartment building after renovation, showing a clean, white exterior wall and a balcony. The number '2' is visible.	 A view of the flat roof after renovation, showing a clean, light-colored surface with a central antenna tower and pipes.